

•

This default PDF was generated via NestForms. You can <u>clone this example form</u> <u>into your account</u>, start collecting and exporting data into this template in seconds.

Report details for the Event - John Doe 253 5236

John Doe 253 5236 - David Charles

25/01/2024

Inspector Details

Question	Answer
Name	John Doe
ID Number	253
Email Address	jd#####@gmail.com
Contact Phone Number	0123456789

Initial Inspection Checklist

Question	Answer
Inspection Serial Number	5236
Location / Area	Sand Banks
GPS Location	55°32'12"N 3°29'51"W
Type of Inspection	Telegraph Poles
Have any of the utilities been recently upgraded or replaced?	No



Question	Answer
Are there any apparent power outages in the area?	No
Are there any unusual maintenance or repair needs that need to be addressed?	Yes
No, Please Describe	Comments: Cables sagging collapsing pole - Health and Safety and Site Inpection / audit and checklists required
Are all utility meters visible and working?	N/A
Is there anything else the surveyor should know about the energy and utilities situation in the area?	Yes
Any other issues, please describe and take images	Comments: Nature survey required / working within protected natural location. Use Land survey app



Inspector Sign Off

Question	Answer
Signature	Mu
Date & Time	25/01/2024