

This default PDF was generated via NestForms. You can <u>clone this example form</u> into your account, start collecting and exporting data into this template in seconds.

Report details for the Event - George Graham _

George Graham _ - Admin Template

24/07/2024

Project Manager Details

Question	Answer
First Name	George
Last Name	Graham
Contact Email:	ggraham####@gmail.com
Contact Tel Number:	01234 567###

Final Inspection Details

Question	Answer
Project Serial Number	12345
Inspection Location	52°33'0"N 7°50'17"W
<i>Is the property clean and free of debris?</i>	Νο



Question	Answer
Comments & Images	Somments: Packaging to be removed from hallway ASAP
<i>Is the paint and wall finish in good condition?</i>	Yes
Are all lights and electrical fixtures in working condition?	Yes
Are all doors and windows functioning properly?	Yes
<i>Is the plumbing system leak-free and fully operational?</i>	Yes
Are there any signs of pest infestation?	Νο
Is the HVAC system functioning properly?	No
Comments & Images	Comments: Contactor needs replaced. Moved to Snag list



Question	Answer
<i>Is the smoke detector working and batteries replaced?</i>	Yes
Date of Snag List completion	13/08/2024

Project Manager Sign Off

Question	Answer
Signature	
Date & Time	24/07/2024